



## NOTIFICATION OF PART CLEAN OF VENTILATION SYSTEM TO TR19<sup>®</sup> SPECIFICATION

**Certificate Number:** BES/1000100861

---

**Site Cleaned:** Chivenor House  
Drem Croft  
Birmingham  
West Midlands  
B35 7HY

---

**Date Clean Undertaken:** 06 March 2025

**Post Clean Verification Report Date:** 13 March 2025

**Post Clean Verification Report Reference:** 82885

**Recommended Date of Next Clean:** 06 March 2026

**BESA Vent Hygiene Register Member**  
Ductbusters Limited  
HV006128

---

**It should be noted that cleaning frequencies are indicative only and are based on historic usage of the system. They should not be seen as substitutes to an actual cleanliness risk assessment undertaken by a competent person. When calculating the cleaning frequency seasonal variations and changes in the type and frequency of cooking should be taken into consideration. An additional risk assessment may be required as a result.**

BESCA and BESA take no responsibility for standard of works undertaken by any third party. Works undertaken are between the Vent Hygiene Register member and the client as named above. This certificate should be read in conjunction with the PCVR referenced above.